

## CONFIRMATION OF ANNUAL DIKE INSPECTION 2004 COLD SPRING CREEK FLOOD CONTROL WORKS

Please complete and return this form.

<u>TC</u>	<u>):</u>	FROM:					
Office of Inspector of Dikes Lower Mainland Regional Office Environmental Protection Division Ministry of Water, Land and Air Protection 10470 - 152nd St Surrey, BC V3R 0Y3		BRIAN FUNKE ENGINEERING TECHNICIAN REGIONAL DISTRICT OF EAST KOOTENAY					
F.A	X: (604) 930-7119						
1.	Is your Annual (2004) Dike Inspection Complete?	YES V NO					
	If NO, please indicate expected completion date:						
	If YES, please provide date of inspection: YY <u>2004</u> MM <u>3</u> DD <u>7</u>						
	and attach the complete inspection report.						
2.	Have there been any recent changes to your address, contact names, phone, email and/or fax numbers? YES NO						
	If YES, please provide details below:						
	·						
3.	If you have any additional comments or suggestions p	blease indicate them below:					
	Submitted by: BRIAN FUNKE	Phone: (250) 489 - 2191					
	Date: APRIL 7, 2005						
	MINDER  e Flood Protection Works Inspection Report should be writte  demonstrate due diligence and eligibility for disast  provide information for flood planning						

Dike's auditing and monitoring procedure. Refer to the publication" Flood Protection Works -Inspection Guide "(March, 2000) for details.

• ensure safe operation and proper maintenance.

Providing a copy of the Annual Flood Protection Works Inspection Report to the Deputy Inspector of Dikes helps to assist in provincial flood planning and provides a basis for the Office of the Inspector of

## Flood Protection Works Management Checklist

Diking	Authority: REGIONAL I	ASTRICT OF 1	EAST KOOTEN	
O&M S	Supervisor: BRIAN FUNK	₹ Tel: 250-49	39.279  Fax: 25	0.489.1287
DIOD:	DWAIN BOYER	Tel: <u>250-354</u>	.6388 Fax: 25	0.354.6332
Dike N	ame: COLD SPRING C	REEK FLOOT	CONTROL (	WORKS
O&M N	Manual:	Yes 🗖	No 🗷	
Floodp	lain Management Bylaw:	Yes 🖸	No 🗅	
1.	Records: Design Reports	REID (ROLUTHER EB. 2, 1995	Plans REID COOL	UTHER
	Files Nos.	Floodpl	ain Maps BYLAW	#1034 SCHODULE B
2.	Rights-of-way:	Yes 🔂	No □	sheer 3
3.	Annual Budget/Taxes:	Yes 🗹	No 🗅	
4.	Follow-up Last Inspection:	Ву:	·	
	Annual Inspection (submit repo	rt to DIOD): Ye	s 🖸 No	a
5.	Approvals/Changes:	Yes 🗅	No 🔼	
6.	Maintenance:	Required	Okay	
	Access: gates	u 0	⊠ ⊠	
	dike crest	ā	123	
	Damages/Repairs:	<b>8</b> 1		
	dike	<b>≥</b>	٥	
	bank protection	<u> </u>	8	
	floodboxes	N/A 0		
	pumps	N/A 0	<b>□</b>	
	drainage Vegetation Control:	٥	2	
	animal activity	ā	Ø	•
	debris		B	
7.	Flood Response Plan:			
	Flow Forecasting	<u> </u>	<u> </u>	
	Contact list	8		
	Materials	<b>⊠</b>	D B	
	Equipment Communications	0	<u>2</u>	
	Flood Patrol	<u> </u>	<u>.</u>	
	Warning/Evacuation Plan	8	Ö	
8.	Follow-up Action Complete: (submit report to DIOD)	Yes 🗅	No 🗆	
	1 2005	G: 1	K2	Co.

Sheet I	No	Ĺ	
File !	No.LL	Eff	B16002

## FLOOD PROTECTION INSPECTION REPORT

Dike Length:						
DIKE: COLD SPRING CREEK FLOOD CONTROL WORKS						
REACH: COLD SPRING CREEK						
DATE INSPECTED: JUNE 7, 2004 Signed: B 26						
The condition of the flood protection works is as reported below:						
<ol> <li>DIKES: (access, gates, locks, vegetation growth, gravel surface, height, stopes, erosion, animal burrows, seepage, trash, berms, relief wells)</li> </ol>						
- A DEFLECTION BERM WEST AND						
PARALLEL TO HIGHWAY 93/95 WAS						
REMOVED.						
- UPSTREAM DEBRIS RESERVOIR REDUIRES						
REPLACEMENT OF TOP TWO STOP LOGS.						
2. BANK PROTECTION: (loss of rock, settlement, slumping)						
BANK PROTECTION APPEARS TO BE						
SATISFACTORY						
<ol> <li>FLOODBOXES/PUMP STATIONS: (inlet and outlet channels, gate operation, trash racks, debris, erosion, corrosion, structure, discharge structure, electrical and mechanical components)</li> </ol>						
THE SECONDARY CULVERT UNDER						
HIGHWAY 93/95 WHICH IS USED IF DEBRIS						
FLOWS BLOCK THE FIRST CULVERT WAS						
FILLED AND DECOMMISSIONED, BY THE DEVELOPER						
WITH OUT PERMISSION FROM THE ROCK						
4. WORK REQUIRED:						
AN ENGINEERING ASSESSMENT IS						
PRESENTLY BEING UNDERTAKEN AS A						
PESULT OF THE SECONDARY CULVERT						
BLOCKAGE AND DEFLECTION BERM REMOVAL.						
VIM DUMONT WITH MCELHANNEY IS PROPARING THE REPORT.						
5. ADDITIONAL INFORMATION: (see over) (sketch, photos, etc.)						
6. WORK COMPLETED: Date: Signed:						