



Please mail or fax this form to the Inspector of Dikes by May 31, 2007

CONFIRMATION OF ANNUAL DIKE INSPECTION 2007

TO:	FROM:
Office of Inspector of Dikes Lower Mainland Regional Office Water Stewardship Division Ministry of Environment 10470 - 152nd St Surrey, BC V3R 0Y3 FAX: (604) 582-5235	Kevin Paterson East Kootenay Regional District 19 - 24th Ave. S. Cranbrook BC V1C 3H8 250-489-2791 Fax 250 489-1287 E-Mail http://www.civicnet.gov.bc.ca
 Is your Annual (2007) Dike Inspection Completed If NO, please indicate expected completion date of If YES, please provide date of inspection: YY and attach the complete inspection report. According to the Provincial Flood Protection We contact person. Is all the information on the about 	orks Database, you are the diking authority
If NO, please provide updated details below - (to case of flood emergencies):	
3. If you have any additional comments or suggest structure, please indicate them below:	tions about your diking authority and/or

Date: __

Submitted by: ___

FLOOD PROTECTION INSPECTION REPORT

Dike Name (From database)	Cold Spring Creek	. GPS No. (databas	e)	330	
Water Courses	Cold Spring Creek	Dike Section	$\overline{\mathcal{R}}_{i}$	erise	
Date Inspected		Signed			
	Mhy 16, 2007				
in detail below or on atta Guide" from March 2000	se check the applicable box. If achments. Please also refer to "In for a detailed guide to dike inspected by the control of th	Flood Protection We pection and reporting	orks Ins ig, avai	pection lable at	· }
. Is there any obstruction, deterioration or damage to dike access? (access outes, ramps, and gates)		YES	NO	N/A	
			<u> </u>		<u> </u>
2. Is there any deteriorat	tion or damage to the following?		YES	NO	N/A
 Dike Crest and slopes 	(ruts, loss of surfacing material, obstruction	s, slumping, cracking)	<u>.</u>	X	
	·				
Bank Protection (loss)	of rock, settlement, slumping)	5		X	
racks, debris, erosion	ations (inlet/outlet channels, gate op , corrosion, structure, mechanical c s?(access routes, ramps, and gates	omponents) or		X	100 mm a
					· · · · ·
3. Were any of the follow attach photo or sketch)	ving serious problems observed?	(if yes, please	YES	NO	N/A
Seepage (and/or evidence)	ence of piping)			X	,
	,			1 <u></u>	<u> </u>
• Erosion				X	
- 					,
Slumping, cracking, si	nk holes		 ;	X	
Animal Damage (heave)	ors, animal burrows, cattle, etc.)				<u> </u>
- Villina Banago (osavo					l
Unauthorized construction	ction (excavations, utilities, structures)			X	
					<u> </u>
Channel infilling and a	aggregation		- 	X	
					
 Significant flood levels 	(within free board) within the last 1	2 months		X	
			,		

4. Vegetation Management		YES	NO	N/A
Hampers or prevents access?			X	
Reduces visibility to each toe?				<u> </u>
				L
Trees in or near dike (within 2m from toe) with potential for uproot	ing?	X	<u> </u>	
Small treas line riverine in some locations along	chanel.		·	·
Multi-year vegetation management plan in place?		IX		
Fall removal of small tiers + veg to occur 2	007.			1
·				
		4.2		
	t) complete	ed in the	past 12	
	t) complete	ed in the	past 12	
	t) complete	ed in the	past 12	
nonths:				
5. Describe the work required in the next 12 months and the estin	nated sche		comple	tion:
nonths: \(\sum_{\substack \text{\substack}} \) Describe the work required in the next 12 months and the esting the stack in the stac	nated sche	dule for	comple npletio	tion:
6. Describe the work required in the next 12 months and the esting	nated sche	dule for sed Cor	comple npletio	tion:
5. Describe maintenance work (including vegetation managemen months: 6. Describe the work required in the next 12 months and the esting the managemen months: The Brushing of sinch wegetation lining towards.	nated sche	dule for sed Cor	comple npletio	tion:

Notes on completing this Flood Protection Inspection Report form:

- 1. Please use a separate inspection form for each dike, or section of dike.
- When completing the inspection report, please use the dike name and GPS Number on the provincial database (on web page or as shown on green sheet enclosed with mail out). If you believe there are any errors or omissions in the database, please submit them with the inspection report.
- 3. If you use more than one form for each dike, please indicate the dike section using chainage and/or major landmarks (roads, bridges etc). Please do not use local property names in the inspection report.

FLOOD COTECTION INSPECTION REPORT

4. Vegetation Management	YES	NO	N/A
Hampers or prevents access?		X	
			
Reduces visibility to each toe?		X	
		· / · · · · · ·	
Trees in or near dike (within 2m from toe) with potential for uprooting	g?		
Small trees line riverine in some locations along a	charel.		
Multi-year vegetation management plan in place?			
Fall removal of small trees + veg to occur 200	07.	•	
0			
	_		
5. Describe maintenance work (including vegetation management) months:	completed in the	past 12	
<i>N</i> /A	<u> </u>		
		•	
6. Describe the work required in the next 12 months and the estima	ited schedule for d	omplet	ion:
Item Brushing of small vegetabien lining reverine	Proposed Completion Date		n Date
	Nov 01, 8	207	
			. !
7 Discouling was all all and a language of the	· · · · · · · · · · · · · · · · · · ·		
7. Please list inspection report attachments (photos, sketches etc.)	· · · · · · · · · · · · · · · · · · ·		

Notes on completing this Flood Protection Inspection Report form:

- 1. Please use a separate inspection form for each dike, or section of dike.
- 2. When completing the inspection report, please use the dike name and GPS Number on the provincial database (on web page or as shown on green sheet enclosed with mail out). If you believe there are any errors or omissions in the database, please submit them with the inspection report.
- 3. If you use more than one form for each dike, please indicate the dike section using chainage and/or major landmarks (roads, bridges etc). Please do not use local property names in the inspection report.

East Kootenay Regional District

Water Course Cold Spring Creek Structure Type Dike

Water Course 2 **Ancilliary Works**

GPS Number 330 Structure Length 484 m

Dike Name Cold Spring Creek NAD 83 Map Number Region Southern Interior Floodplain Maps

UTM Northing 5 576 382 Owner/Administrator East Kootenay Regional District

> Address 19 - 24th Ave S **UTM Easting** 11U 580 578

City Cranbrook Service Area Land Use Province BC Residential

Postal Code V1C 3H8 **Number of Buildings Protected**

Contact Person Kevin Paterson Infrastructure Protected Telephone 250-489-2791 Geographic Feature Riverine

> Fax 250-489-1287 Type of Flooding

Local Authority under EPA East Kootenay Regional District

Regulated under DMA Yes

Notes Urban drainage works. Located 250m north of Fairmont Creek