



2012 Fairmont Creek Inspection Report

Water Course 2: Fairmont Creek

GPS Number 52

The dike was inspected on Friday May 11, 2012

Weather conditions at the time of the inspection were mostly sunny, approximately 20⁰ C.

Upstream Conditions

The upstream conditions for Fairmont Creek were normal, limited debris existed within the creek channel.

Dike Conditions

The dike armouring is in good condition with no signs of erosion or high water over the past 12 months. The flow through the channel is similar to last year. Some vegetation is present in the armouring of the dike and removal of the brush is scheduled for the fall of 2012. The brushing was originally scheduled to be removed in the fall of 2011, but due to RDEK personnel availability the vegetation removal was postponed to 2012. (please see attached photos)

Scheduled Maintenance

Removal of vegetation from the dike armouring is scheduled for the fall of 2012.

Maintenance Executed over the Past 12 Months

Other than annual reporting and inspections, no maintenance was undertaken in 2011.

Fairmont Creek Flow above Armoured Works



Top Section of Armouring





Bottom Section of Armouring